

# Utility Licence Annual Report 2023-24

Licence utility:	Evoenergy
Utility service:	electricity distribution
Number of parts to report:	8

### Parts to report

- Part A Utilities Act
- Part B Consumer Protection Code
  - <u>B1 Customer Protection</u>
  - <u>B2 Guaranteed Service Levels</u>
  - <u>B3</u> Rebates paid against guaranteed service levels
- Part C Utilities (Electricity Feed-in Code)
- Part D Utility licence conditions

# Providing data and information to the Commission

Please read the Utility Licence Annual Report Guideline for a more detailed instructions on providing relevant and quality information to the Commission.

• All responses provided should only relate to services provided in the ACT. In the event the licensee is unable to disaggregate ACT services from other jurisdictions, the licensee must provide a statement detailing: area that the dataset covers, brief explanation why data cannot be disaggregated, additional information that may assist the Commission in understanding the approximate percentage of services that are provided in the ACT from the dataset.

• All licensed utilities must provide information and data in the report that are within the reporting period. Data must be provided even if a nil (zero) figure is recorded.

1 July 2023 to 30 June 2024
by 1 October 2024
icrc@act.gov.au

Please submit the completed report in MS excel format.

• If the licensee is not able to provide the data or answer a question required in the report, the licensee should indicate 'not available' and provide supplementary information detailing why the information is not available and whether (and in what timeframe) it intends to collect this data.

• In most cases a response of 'yes', 'no', 'not applicable' or a figure will suffice. An explanatory statement or supplementary information (e.g. copies of policies or procedures or a link to material on the internet) maybe required.

• Where data is not available the licensee must provide other data that could serve a similar purpose as the data requested (i.e. data that could equally indicate the level of licensee compliance and identify possible causes of non-compliance). Such data should be clearly identified in the report together with an explanation of the alternative taken.

• The licensee should provide commentary where there is a need to explain key factors relevant to the level of, and trends in, their performance. If the licensee response represents a significant variation in the data from the previous reporting period, additional information is to be provided on the cause(s) of the variation. Any supplementary information can be provided in the comments column, or in an attachment. Where applicable, include measures or actions to be put in place to address or rectify the reported variation. All comments must be put in the comment section box.



# Part A — Utilities Act

Ref Our tracking number	Reporting requirements Damage etc. to be minimised (Section 108)	Response Answer n/a if the data requested is not available. Answer "0" if data recorded is nil or zero Data must relate only to the 2023-24 reporting period unless specified otherwise.	Additional comments Please provide information that you feel is relevant and will assists us in our assessment such as an explanation or a reason/s for significant variances from the previous year.
A101	Number of complaints received about any inconvenience, detriment or damage to landholders' property resulting from network operations.	1	Review of work outcomes leading to improved methodologies and improved customer outcomes.
A101(a)	Provide details of the type of complaints received and actions taken to address the complaints.		Customer complained of impact to property due to vehicle position during reactive works. Complaint was investigated and dismissed as no grounds for compensation.
	Notice to landholders to undertake network operations (Secti	on 109)	
A102	Number of times the licensee failed to give the landholder at least seven days notice of a proposed network operation.	1	On one occasion during this FY Evoenergy failed to provide notification to the landholder. No damage was reported.
A103	Number of complaints received about carrying out operations in urgent circumstances under section 109(5).	0	
A103(a)	Provide details of the type of complaints received and actions taken to address the complaints.		Customer complained that crew entered property without notification to complete work. Issue investigated, no damage to property.
	Notice about lopping trees etc. on private land (Section 110)	1	
A104	Number of times the licensee failed to give the landholder seven days notice.	0	

A105	Number of complaints received related to carrying out tree related activities in urgent circumstances under section 110(8).	0	
A105(a)	Provide details of the type of complaints received and actions taken to address the complaints.	N/A	
	Network operations affecting heritage significance (Section 1	10A)	
A106	Number of notices given under sections 109 and 110 that may have affected a place or object of heritage significance under section 110A.		There were zero notices, incidents or directions issued under section 109, 110 or 110A during the reporting period.
A107	Number of notices under section 110A where the licensee failed to provide copies to the heritage council at least seven days before the network operation.		There were zero notices, incidents or directions issued under section 109, 110 or 110A during the reporting period.
A108	Number of complaints receieved relating to operations undertaken pursuant to s 110A(2).		There were zero notices, incidents or directions issued under section 109, 110 or 110A during the reporting period.
A108(a)	Provide details of the type of complaints received and actions taken to address the complaints.		There were zero notices, incidents or directions issued under section 109, 110 or 110A during the reporting period.
	Notice to other utilities (Section 111)		
A109	Number of complaints received for failing to give seven days notice to other public utilities before performing network operations on their land that potentially affected network facilities under the care and management of those utilities.	0	
A109(a)	Provide details of the type of complaints received and actions taken to address the complaints.	0	
A110	Number of complaints received for carrying out network operations in urgent circumstances under section 111(6).	0	
A110(a)	Provide details of the type of complaints received and actions taken to address the complaints.	0	
	Removal of utility's property and waste (Section 112)		
A111	Number of network operations where the licensee failed to remove as soon as practicable from the land, for which it was not the landholder, items listed in section 112(1).	0	N/A
A112	number of complaints received for failing to remove as soon as practicable from the land for which it was not the landholder, any items listed in section 112(1).	0	N/A

A112(a)	Provide details of the type of complaints received and actions taken to address the complaints.	0	N/A
	Land to be restored (Section 113)		
A113	Number of complaints received for failing to ensure, as soon as practicable, that the land was restored to a condition that was similar to its condition before the operations began.	0	
A113(a)	Provide details of the type of complaints received and actions taken to address the complaints.		N/A
	Authorised persons (Division 7.4)		
A201	Were all persons authorised under section 114 (Authorised Persons) issues with photographic identity cards?	Yes	Employees are issued with a security ID pass on employment. An Internal Authorised worker is issued with a virtual ID pass once they have met the training requirements outlined in the Electrical Safety Rules part 3. An external worker is issued with a virtual ID pass once they meet the requirements of the Authorisation and Accreditation process and have met the training requirements outlined in the Electrical Safety Rules, table 3.2. Refer https://www.evoenergy.com.au/Safety/Working- near-the-network for more information and resources.
A202	Are authorised persons made aware of their obligations and entry restrictions under the Utilities Act?	Yes	The Electrical Safety Rules training teaches safe approach distance (distances they can/cannot work within). Service and Installation Rules training provides requirements when accessing a customer premises.
A202(b)	Provide details of any induction or special training to authorised persons to educate them about their obligations and entry restrictions under the Utilities Act. Please include whether the training is provided on a regular or ad hoc basis.	Yes	Electrical Safety Rules training, aligned to national unit of competency UETTDRRF01A is provided on a 12 monthly basis; refer https://training.gov.au/Training/Details/UETTDRRF0 1. Service and Installation Rules provided every 12 months.

A203	Number of written directions received from the ACAT under section 179(2).	N/A	Nothing to report
	Discharge of customer debt (Section 180)		
A204	Number of written declarations received from the ACAT under section 180(1).	N/A	Nothing to report
	Payment for loss or damage (Section 181)		
UA205	Number of written directions received from the ACAT under section 181(1) to pay a stated amount to a complainant for a loss or damage.	1	ACAT EW Complaint 2024-0006 Client 16315 Whalan
A205(a)	Provide details of each direction including stated action/s and the licensee's compliance with the direction.	Directions issued 19/4/24	By Consent: 1. The complaint application is dismissed AND IT IS NOTED 2. The Respondent Utility agrees to pay an amount of \$15,000 to the Applicant without admission of liability; and 3. Payment to b made by 30 April 2024.
	Community service obligations (Part 13)		
or other so	se of Part 13 of the Act is: (a) to oblige utilities to provide utility services in accord ocial issues; and (b) to achieve that results by agreement with particular utilities or sonable recompense for the provision of services in accordance with such direction	; where agreement is not reached, by	
A206	Number of directions received under section 221 from the minister responsible for a government program that required the licensee to provide utility services in accordance with the relevant government program.	0	Refer to the FY23-24 Ministerial report for more information.
A207	Provide details of each direction including stated action/s and the licensee's compliance with the direction. Provide a summary with respect to the relevant government program.	N/A	
A208	Provide details for each direction of the determination of costs provided under sections 222, 223 and 219(c).	N/A	

END OF A1



#### Part B — Consumer Protection Code

#### B1 — Customer Protection

Ref	Reporting requirements	Response	Additonal comments
Our tracking		Answer n/a if the data requested is not available. Answer "0" if data recorded is nil or zero.	Please provide any information that you feel is relevant to support us in our assessment such as reason/s for non-compliance and actions taken to rectify the non-compliance and minimise future occurrences.
number			
		Data must relate only to the 2023-24 reporting period	When applicable, please also provide an explanation or a reason/s for significant variances from the previous year.
Complet	nts procedures (6.1 and 6.2)	unless specified otherwise.	
-	Does the licensee's complaint handling procedures address all		Evoenergy provides the Customer Charter in English, large print (English) as well as the top 5 spoken non-English languages in the ACT.
D101	requirements of clause 6.1 of the Code?	Yes	evenergy provides the customer charter in English, large print (English) as well as the top 5 spoken non-english languages in the ACL.
B101(a)	Provide a copy (or a link to a copy) of the utility's complaint handling	Evoenergy Customer Charter -	Hindi, Simplified Chinese, Traditional Chinese, Spanish, and Vietnamese. These languages were based upon ABS data for the ACT: 2016 Census Data for the top 5 most spoken
BIUI(a)	procedures		language in the Territory other than English
	procedures	rights-and-obligations	
B102	Which version of the Australian Standard does your complaints	Guidelines for complaints management in	
	handling policy and procedures comply with?	organisations (AS/NZ 10002:2014).	
	ing complaints (6.3)	organisations (AS/NZ 10002.2014).	
	How and when are customers or consumers advised of the utility's		Link to complaint procedure on website - https://www.evoenergy.com.au/About-us/Contact-us
	complaints handling procedures?	Consumers are advised of the license's complaints	Link to complaint procedure on website - https://www.evoenergy.com.au/About-us/contact-us
		handling procedure on our website, and at the	
		complaint acknowledgement stage (via email or	
1		verbally).	
B104	How and when are customers or consumers advised of their right to	verbaily).	
0104	refer a complaint to the ACAT?		
		Information regarding consumers' right to lodge a	
		complaint with ACAT is contained within	
		Evoenergy's Complaints and Dispute Resolution	
		Procedure published on the Evoenergy website.	
		Consumers are personally advised of their right to	
		lodge a complaint with ACAT at the complaint	
		acknowledgement and meaningful response steps	
		(via email or verbally). This advice is also provided	
		when responding to reconsidered or escalated	
		complaints. Additionally, all Evoenergy customer	
		access notifications refer to ACAT and Evoenergy	
Litility to	keep records (6.4)	obligations under the Utilities Act 2000.	
-	Are records of complaints made by a customer or consumer kept for at	Vac	Evoenergy records the details of complaints in our system and retains this information for a minimum of 7 years.
BIUJ	least 12 months after the complaint is resolved?	les	Evening records the details of complaints in our system and recards this information for a minimum of 7 years.
Number	of complaints		
	Total number of complaints received	73	This figure represents a 65% decrease in the number of complaints received during the previous reporting period.
	wn of complaints per category		
Ref	Complaint category	Number of complaints	Additional comments
	Connection took too long	1	
	Damage / fault our asset	1	
B106(c)	Damage to environment	0	
B106(d)	Damage to property	5	One issue was related directly to damage to property and the other four were related to damage to appliances at the property.
B106(e)	Disconnection	2	Sine use has reaced an easily to damage to property and the other roat more related to damage to appliance at the property.
\ - /	Electricity quality	6	These related to issues of low voltage. The matters were investigated and either resolved or remain under investigation.
B106(g)	Entry to land	0	
B106(h)	Failed to reply	0	
B106(i)	Fee dispute	15	Mostly issues related to vegetation fees disputed for the clearing of network infringements where this has not been managed by the landholder.
	Feed-in tariff	1	
B106(k)	Information wrong	1	
B106(I)	Late / missed appointment	1	
	Meters, meter readings	2	
5100(11)	increasy increasings	I-	1

B106(n)	Network charges	0					
B106(o)	Inadequate notice of work	0					
B106(p)	Noise / unsightly	0					
B106(q)	Not told outage cancelled	0					
B106(r)	Service request not met	1					
B106(s)	Site restoration	0					
B106(t)	System unreliability	4					
B106(u)	Other (if the licensee has additional categories not listed, please also	21					
	provide details of the categories)						
	Other staff misbehaviour	0					
	Outage notice nil / too short	0					
	Outage too long	1					
	Staff rude	3					
	Telephone service poor	2					
	Timing of work	6	The concerns were related	to work close to Christmas and o	on a weekend. All works were revi	iewed and deemed r	necessary.
	Trees in wires	0					·
	Work faulty	0					
	Note: Press tab on your keyboard to start a new line.						
Summa	ry of Consumer and Utility Rights (Clause 9)						
B107	Was the licensee compliant with all the requirements in clause 9.3?	Yes					
B108	Provide a copy of the licensee's statement summarising the rights of a		Evoenergy provides the Cu	istomer Charter in English, large p	print (English) as well as the top 5	spoken non-English	languages in the ACT.
	consumer and the licensee under the Utilities Act, the Consumer	Evoenergy Customer Charter					
	Protection Code and the relevant customer contract.	https://www.evoenergy.com.au/Your-Energy/Your-					
		rights-and-obligations					
B109	What languages is the summary available in?	Hindi, Simplified Chinese, Traditional Chinese,	These languages were base	ed upon ABS data for the ACT: 20	16 Census Data for the top 5 mos	t spoken language ir	the Territory other than English
1 :6		Spanish, and Vietnamese.					
	port (Clause 10)						
B110	Number of instances where the licensee failed to provide at least 4		Details in table below				
	business days' notice of a planned interruption to a registered life	3					
D440(-)	support equipment supply address.	Least the stress dealer stress for shore a little second stress		Al	all and the second for fall as		den se tra la calencia de arte contra constructivo de la construcción de la construcción de la construcción de
B110(a)	Please give details on every instance as to why you failed to provide at	least 4 business days' notice of a planned interruption	to a registered life support	equipment supply address. Also	please provide reason for failure	to meet the require	d service level and actions taken to rectify the non-compliance
B110(a)		L least 4 business days' notice of a planned interruption	to a registered life support	equipment supply address. Also	please provide reason for failure	to meet the require	d service level and actions taken to rectify the non-compliance
B110(a)	Please give details on every instance as to why you failed to provide at		to a registered life support		please provide reason for failure What was the effect to the customer	to meet the required	d service level and actions taken to rectify the non-compliance Remediation
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report.	Least 4 business days' notice of a planned interruption Date of planned interruption enter as dd/mm/yyyy		equipment supply address. Also Reason for the non-compliance provide a reason(s) for not giving			-
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code	Date of planned interruption	Duration of planned	Reason for the non-compliance	What was the effect to the customer with registered life support? We will use your response to assess	Was the incident	Remediation
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code	Date of planned interruption	Duration of planned interruption	Reason for the non-compliance provide a reason(s) for not giving	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the	Was the incident reported to the AER?	Remediation provide details of actions taken to rectify the non-compliance and minimise
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code	Date of planned interruption	Duration of planned interruption	Reason for the non-compliance provide a reason(s) for not giving	What was the effect to the customer with registered life support? We will use your response to assess	Was the incident reported to the AER?	Remediation provide details of actions taken to rectify the non-compliance and minimise
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code	Date of planned interruption	Duration of planned interruption	Reason for the non-compliance provide a reason(s) for not giving	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the	Was the incident reported to the AER?	Remediation provide details of actions taken to rectify the non-compliance and minimise
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code	Date of planned interruption	Duration of planned interruption	Reason for the non-compliance provide a reason(s) for not giving	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the	Was the incident reported to the AER?	Remediation provide details of actions taken to rectify the non-compliance and minimise
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code Your reference code	Date of planned interruption enter as dd/mm/yyyy	Duration of planned interruption enter as hours:minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe Incorrect labelling at the substation. Inconsistency	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customer is serious or not. Customers without supply for approximately 38 minutes.	Was the incident reported to the AER? answer Y/N	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code Your reference code	Date of planned interruption enter as dd/mm/yyyy	Duration of planned interruption enter as hours:minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe Incorrect labelling at the substation. Inconsistency between the Advanced	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customer is serious or not. Customers without supply for approximately 38 minutes. Restoration of supply commenced	Was the incident reported to the AER? answer Y/N	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code Your reference code	Date of planned interruption enter as dd/mm/yyyy	Duration of planned interruption enter as hours:minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customer is serious or not. Customers without supply for approximately 38 minutes. Restoration of supply commenced immediately, following	Was the incident reported to the AER? answer Y/N	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code Your reference code	Date of planned interruption enter as dd/mm/yyyy	Duration of planned interruption enter as hours:minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customer is serious or not. Customers without supply for approximately 38 minutes. Restoration of supply commenced	Was the incident reported to the AER? answer Y/N	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried out to determine root cause of incident and identify oportunities
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code Your reference code	Date of planned interruption enter as dd/mm/yyyy	Duration of planned interruption enter as hours:minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customer is serious or not. Customers without supply for approximately 38 minutes. Restoration of supply commenced immediately, following	Was the incident reported to the AER? answer Y/N	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code Your reference code	Date of planned interruption enter as dd/mm/yyyy	Duration of planned interruption enter as hours:minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration. An error was made by the	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customer is serious or not. Customers without supply for approximately 38 minutes. Restoration of supply commenced immediately, following identification of the error. Customers without supply for	Was the incident reported to the AER? answer Y/N	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. Electrical officer immediately began the process to restore supply
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report.  Reference code Your reference code 17229	Date of planned interruption enter as dd/mm/yyyy 15/8/23	Duration of planned interruption enter as hours:minutes 38 minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration. An error was made by the electrical officer restoring supply	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customer is serious or not. Customers without supply for approximately 38 minutes. Restoration of supply commenced immediately, following identification of the error.	Was the incident reported to the AER? answer Y/N Yes	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. Electrical officer immediately began the process to restore supply to impacted customers by restoring the LV back-feed and
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report.  Reference code Your reference code 17229	Date of planned interruption enter as dd/mm/yyyy 15/8/23	Duration of planned interruption enter as hours:minutes 38 minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration. An error was made by the electrical officer restoring supply with a step missed in the	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customer is serious or not. Customers without supply for approximately 38 minutes. Restoration of supply commenced immediately, following identification of the error. Customers without supply for	Was the incident reported to the AER? answer Y/N Yes	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. Electrical officer immediately began the process to restore supply to impacted customers by restoring the LV back-feed and proceeding with correct order of the switching plan. Full
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report.  Reference code Your reference code 17229	Date of planned interruption enter as dd/mm/yyyy 15/8/23	Duration of planned interruption enter as hours:minutes 38 minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration. An error was made by the electrical officer restoring supply with a step missed in the restoration process that resulted	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customer is serious or not. Customers without supply for approximately 38 minutes. Restoration of supply commenced immediately, following identification of the error. Customers without supply for	Was the incident reported to the AER? answer Y/N Yes	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. Electrical officer immediately began the process to restore supply to impacted customers by restoring the LV back-feed and proceeding with correct order of the switching plan. Full investigation carried out to determine root cause of incident and
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report.  Reference code Your reference code 17229	Date of planned interruption enter as dd/mm/yyyy 15/8/23	Duration of planned interruption enter as hours:minutes 38 minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration. An error was made by the electrical officer restoring supply with a step missed in the	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customer is serious or not. Customers without supply for approximately 38 minutes. Restoration of supply commenced immediately, following identification of the error. Customers without supply for	Was the incident reported to the AER? answer Y/N Yes	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. Electrical officer immediately began the process to restore supply to impacted customers by restoring the LV back-feed and proceeding with correct order of the switching plan. Full
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report.  Reference code Your reference code 17229	Date of planned interruption enter as dd/mm/yyyy 15/8/23	Duration of planned interruption enter as hours:minutes 38 minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration. An error was made by the electrical officer restoring supply with a step missed in the restoration process that resulted	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customer is serious or not. Customers without supply for approximately 38 minutes. Restoration of supply commenced immediately, following identification of the error. Customers without supply for	Was the incident reported to the AER? answer Y/N Yes	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. Electrical officer immediately began the process to restore supply to impacted customers by restoring the LV back-feed and proceeding with correct order of the switching plan. Full investigation carried out to determine root cause of incident and
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code Your reference code 17229 17255	Date of planned interruption enter as dd/mm/yyyy 15/8/23 31/8/24	Duration of planned interruption enter as hours:minutes 38 minutes 5 minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration. An error was made by the electrical officer restoring supply with a step missed in the restoration process that resulted in 30 customers to lose supply.	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customer is serious or not. Customers without supply for approximately 38 minutes. Restoration of supply commenced immediately, following identification of the error. Customers without supply for approximately 5 minutes.	Was the incident reported to the AER? answer Y/N Yes	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. Electrical officer immediately began the process to restore supply to impacted customers by restoring the LV back-feed and proceeding with correct order of the switching plan. Full investigation carried out to determine root cause of incident and identify oportunities for improvement.
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code Your reference code 17229 17255	Date of planned interruption enter as dd/mm/yyyy 15/8/23 31/8/24	Duration of planned interruption enter as hours:minutes 38 minutes 5 minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration. An error was made by the electrical officer restoring supply with a step missed in the restoration process that resulted in 30 customers to lose supply. Incorrect labelling at the substation. Inconsistency between the Advanced	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customer is serious or not. Customers without supply for approximately 38 minutes. Restoration of supply commenced immediately, following identification of the error. Customers without supply for approximately 5 minutes. 2 Life Support customers lost supply for approximately 2 hours, 50 minutes. Restoration of supply was	Was the incident reported to the AER? answer Y/N Yes	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. Electrical officer immediately began the process to restore supply to impacted customers by restoring the LV back-feed and proceeding with correct order of the switching plan. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. At the time the breach was confirmed, the pillar had already been removed as part of planned network maintenance. The crew continued with the installation of the new pillar to restore supply as
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code Your reference code 17229 17255	Date of planned interruption enter as dd/mm/yyyy 15/8/23 31/8/24	Duration of planned interruption enter as hours:minutes 38 minutes 5 minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required time/rame lincorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration. An error was made by the electrical officer restoring supply with a step missed in the restoration process that resulted in 30 customers to lose supply. Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customer is serious or not. Customers without supply for approximately 38 minutes. Restoration of supply commenced immediately, following identification of the error. Customers without supply for approximately 5 minutes. 2 Life Support customers lost supply for approximately 2 hours, 50 minutes. Restoration of supply was completed as soon as possible. The	Was the incident reported to the AER? answer Y/N Yes	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. Electrical officer immediately began the process to restore supply to impacted customers by restoring the LV back-feed and proceeding with correct order of the switching plan. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. At the time the breach was confirmed, the pillar had already been removed as part of planned network maintenance. The crew continued with the installation of the new pillar to restore supply as soon as possible. Full investigation carried out to determine root
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code Your reference code 17229 17255	Date of planned interruption enter as dd/mm/yyyy 15/8/23 31/8/24	Duration of planned interruption enter as hours:minutes 38 minutes 5 minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe lincorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration. An error was made by the electrical officer restoring supply with a step missed in the restoration process that resulted in 30 customers to lose supply. Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customer is serious or not. Customers without supply for approximately 38 minutes. Restoration of supply commenced immediately, following identification of the error. Customers without supply for approximately 5 minutes. 2 Life Support customers lost supply for approximately 2 hours, 50 minutes. Restoration of supply was completed as soon as possible. The planned network maintenance was	Was the incident reported to the AER? answer Y/N Yes	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. Electrical officer immediately began the process to restore supply to impacted customers by restoring the LV back-feed and proceeding with correct order of the switching plan. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. At the time the breach was confirmed, the pillar had already been removed as part of planned network maintenance. The crew continued with the installation of the new pillar to restore supply as
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code Your reference code 17229 17255	Date of planned interruption enter as dd/mm/yyyy 15/8/23 31/8/24	Duration of planned interruption enter as hours:minutes 38 minutes 5 minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe lincorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration. An error was made by the electrical officer restoring supply with a step missed in the restoration process that resulted in 30 customers to lose supply. Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customers without supply for approximately 38 minutes. Restoration of supply commenced immediately, following identification of the error. Customers without supply for approximately 5 minutes. 2 Life Support customers lost supply for approximately 2 hours, 50 minutes. Restoration of supply was completed as soon as possible. The planned network maintenance was completed in order to re-establish	Was the incident reported to the AER? answer Y/N Yes	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. Electrical officer immediately began the process to restore supply to impacted customers by restoring the LV back-feed and proceeding with correct order of the switching plan. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. At the time the breach was confirmed, the pillar had already been removed as part of planned network maintenance. The crew continued with the installation of the new pillar to restore supply as soon as possible. Full investigation carried out to determine root
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code Your reference code 17229 17255	Date of planned interruption enter as dd/mm/yyyy 15/8/23 31/8/24	Duration of planned interruption enter as hours:minutes 38 minutes 5 minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe lincorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration. An error was made by the electrical officer restoring supply with a step missed in the restoration process that resulted in 30 customers to lose supply. Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration which was not identified by	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customer is serious or not. Customers without supply for approximately 38 minutes. Restoration of supply commenced immediately, following identification of the error. Customers without supply for approximately 5 minutes. 2 Life Support customers lost supply for approximately 2 hours, 50 minutes. Restoration of supply was completed as soon as possible. The planned network maintenance was	Was the incident reported to the AER? answer Y/N Yes	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. Electrical officer immediately began the process to restore supply to impacted customers by restoring the LV back-feed and proceeding with correct order of the switching plan. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. At the time the breach was confirmed, the pillar had already been removed as part of planned network maintenance. The crew continued with the installation of the new pillar to restore supply as soon as possible. Full investigation carried out to determine root
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code Your reference code 17229 17255	Date of planned interruption enter as dd/mm/yyyy 15/8/23 31/8/24	Duration of planned interruption enter as hours:minutes 38 minutes 5 minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe lincorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration. An error was made by the electrical officer restoring supply with a step missed in the restoration process that resulted in 30 customers to lose supply. Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration which was not identified by scoping in the works planning	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customers without supply for approximately 38 minutes. Restoration of supply commenced immediately, following identification of the error. Customers without supply for approximately 5 minutes. 2 Life Support customers lost supply for approximately 2 hours, 50 minutes. Restoration of supply was completed as soon as possible. The planned network maintenance was completed in order to re-establish	Was the incident reported to the AER? answer Y/N Yes	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. Electrical officer immediately began the process to restore supply to impacted customers by restoring the LV back-feed and proceeding with correct order of the switching plan. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. At the time the breach was confirmed, the pillar had already been removed as part of planned network maintenance. The crew continued with the installation of the new pillar to restore supply as soon as possible. Full investigation carried out to determine root
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code Your reference code 17229 17255	Date of planned interruption enter as dd/mm/yyyy 15/8/23 31/8/24	Duration of planned interruption enter as hours:minutes 38 minutes 5 minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe lincorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration. An error was made by the electrical officer restoring supply with a step missed in the restoration process that resulted in 30 customers to lose supply. Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration which was not identified by	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customers without supply for approximately 38 minutes. Restoration of supply commenced immediately, following identification of the error. Customers without supply for approximately 5 minutes. 2 Life Support customers lost supply for approximately 2 hours, 50 minutes. Restoration of supply was completed as soon as possible. The planned network maintenance was completed in order to re-establish	Was the incident reported to the AER? answer Y/N Yes	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. Electrical officer immediately began the process to restore supply to impacted customers by restoring the LV back-feed and proceeding with correct order of the switching plan. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. At the time the breach was confirmed, the pillar had already been removed as part of planned network maintenance. The crew continued with the installation of the new pillar to restore supply as soon as possible. Full investigation carried out to determine root
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code Your reference code 17229 17255	Date of planned interruption enter as dd/mm/yyyy 15/8/23 31/8/24	Duration of planned interruption enter as hours:minutes 38 minutes 5 minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe lincorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration. An error was made by the electrical officer restoring supply with a step missed in the restoration process that resulted in 30 customers to lose supply. Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration which was not identified by scoping in the works planning	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customers without supply for approximately 38 minutes. Restoration of supply commenced immediately, following identification of the error. Customers without supply for approximately 5 minutes. 2 Life Support customers lost supply for approximately 2 hours, 50 minutes. Restoration of supply was completed as soon as possible. The planned network maintenance was completed in order to re-establish	Was the incident reported to the AER? answer Y/N Yes	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. Electrical officer immediately began the process to restore supply to impacted customers by restoring the LV back-feed and proceeding with correct order of the switching plan. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. At the time the breach was confirmed, the pillar had already been removed as part of planned network maintenance. The crew continued with the installation of the new pillar to restore supply as soon as possible. Full investigation carried out to determine root
B110(a)	Please give details on every instance as to why you failed to provide at Please tick 'Nothing to report' if you have no incident to report. Reference code Your reference code 17229 17255	Date of planned interruption enter as dd/mm/yyyy 15/8/23 31/8/24	Duration of planned interruption enter as hours:minutes 38 minutes 5 minutes	Reason for the non-compliance provide a reason(s) for not giving notice within the required timeframe lincorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration. An error was made by the electrical officer restoring supply with a step missed in the restoration process that resulted in 30 customers to lose supply. Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration which was not identified by scoping in the works planning	What was the effect to the customer with registered life support? We will use your response to assess whether the effect of the incident to the customers without supply for approximately 38 minutes. Restoration of supply commenced immediately, following identification of the error. Customers without supply for approximately 5 minutes. 2 Life Support customers lost supply for approximately 2 hours, 50 minutes. Restoration of supply was completed as soon as possible. The planned network maintenance was completed in order to re-establish	Was the incident reported to the AER? answer Y/N Yes	Remediation provide details of actions taken to rectify the non-compliance and minimise future occurrences Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. Electrical officer immediately began the process to restore supply to impacted customers by restoring the LV back-feed and proceeding with correct order of the switching plan. Full investigation carried out to determine root cause of incident and identify oportunities for improvement. At the time the breach was confirmed, the pillar had already been removed as part of planned network maintenance. The crew continued with the installation of the new pillar to restore supply as soon as possible. Full investigation carried out to determine root



#### Part B — Consumer Protection Code

B2 — Guaranteed Service Levels

Ref		Response			Additonal comments			
Our tracking	Reporting requirements	Answer n/a if the data requested is not availab	sle.		Please provide any information that you feel is relevant to support us in our assessment such as reason/s for non-compliance and actions taken to rectify the non-compliance and			
number		Answer "0" if data recorded is nil or zero.	and the first state of the first state of the		minimise future occurrences.	· · · · · · · · · · · · · · · · · · ·		
		Data must relate only to the 2023-24 reporting	g period unless specified otherwise.		When applicable, please also provide an explanation of	or a reason/s for significant variances from the previo	us year.	
=	to pay rebate for non-compliance (Clause 11)	Please provide more details in <u>B3</u> .			Ι			
B111	Number of GSL rebate payments made		518					
B111(a)	Amount of GSL rebate payments made		60100					
B112	Number of breaches of GSL's where rebates have not been paid		0					
B113	In relation to B112, why have the GSL payment not been made?		N/A					
B115	Number of GSL rebate payments made in the same or next billing		483					
B116	quarter to the quarter the obligation to pay the GSL rebate occurred Number of GSL rebate payments made more than one billing quarter							
	after the quarter the obligation to pay the GSL rebate occured		35		Q2 ac	counted for retrospective payment of 35 GSL E	-4's from November 2022.	
B116(a)	In relation to B116, why were the GSL rebate payments made more than one billing quarter after the quarter the obligation to pay the GSL rebate occurred				Evoenergy identified a failure to pay 35 GSL-4 re	bates following the submission of FY 22.23 ICR immediately upon identifying the	C ULAR reporting. Evoenergy arranged payment of the missed GSLs error.	
Customer	connection times (Guaranteed Service Level 1)							
B201	Number of customer connections not made within the required timeframe specified in the Consumer Protection Code.		150		147 basic connections not completed in time	with the MSO timeframes. 3 incidents of fail. Consumer Protection Code	ure to re-energise within the required timeframe specified in the	
B202	What percentage does this represent of total connections?		4.69%					
Wrongful d	lisconnection (Guaranteed Service Level 2)	L			l.			
B203	Number of wrongful disconnections.		2		System refinement over the past 12 - 18 n	nonths have ensured a more effective process	resulting in a significant reduction of wrongful disconnections.	
B203(a)	Please give details on every instance of a wrongful disconnection. Also,	please provide reason for failure to meet	the required service level and actions taken to	o rectify the non-compliance and mini		•		
	Please tick <u>'Nothing to report'</u> if you have no incident to report.	· ·						
	Reference Your incident reference number	Date customer disconnected enter as dd-mm-yy	Date customer reconnected enter as dd-mm-yy	Reason for failure to meet the required se provide a reason(s) for the wrongful discor		What was the effect to the customer? We will use your response to assess whether the effect of the incident to the customer is serious or not.	Remediation provide details of actions taken to rectify the non-compliance and to minimise future occurrences.	
	17380	14/11/23	16/11/23	Evoenergy Electrical Officer (EO) was performing routine re-energisation (re-en) and i energisation (de-en) services at multiple premises including a request for a re-en at (premise). When the EO arrived at the premise, supply was already energised. With mind, the EO assumed the required service was a de-en and proceeded to unknowlin en the premise in error.		Property without supply for 2 days (customer was not residing at the premises at this time).	Evoenergy re connected the supply on 16/11/23 as soon as possible after becoming aware of the incident. Full investigation carried out to determine root cause of incident and identify oportunities for improvement.	
	Note - this incident was incorrectly paid as a GSL-4 at the time of the incident. The customer should have been paid a GSL-2. This has been rectified in September 2024 GSL rebate payments and will also be reflected in PY24.25 reporting. 17268	7/9/24	7/9/24		disconnection of a service line from an individual trical Officer mistakenly disconnected an adjacent sustomer losing supply.	Life Support Customer without supply for approximately 4 minutes. Restoration of supply commenced immediately following identification of the error.	The EO restored supply immediately after realising error. The EO completed a welfare check on the life support customer in person, knocking on the door to explain the incident which had occurred, and ensuring the wellbeing of the customer. Full investigation carried out to determine root cause of incident and identify oportunities for improvement.	
	Note: Press tab on your keyboard to start a new line.						•	
Respondin	g to complaints (Guaranteed Service Level 3)							
B204	Number of complaints <u>not</u> responded to within 20 business days.		0		Improvement i	n the complaints handling process has resulted	i in all GSL's being met in this area.	
Planned in	terruptions to utility services (Guaranteed Service level 4)				1			

B205	Number of planned interruptions to services.	1274		Impacting 54,843 customers			
B205(a)	Average planned interuption duration		6 hours 26 minutes				
B206	Number of premises that were not provided with at least 4 business days' notice of a planned interruption		202		Incudes the 35 retrospective GSL payments from the incident in November 2022 and 1 customer who was paid a GSL-E4 incorrectly.		
B206(a)	Please give details on every intance where you did not give at least 4 b	usiness days' notice of a planned interruption	on. Also, please provide reasons for non-complia	nces and actions taken to rectify the	non-compliance and minimise future occurrences. If multiple works occurred on the same date	please list each incident separately.	
	Please tick <u>'Nothing to report'</u> if you have no incident to report.						
	Reference code Your reference code	Date of planned interruption enter as dd/mm/yyyy	Number of affected premises	Number of premises not notified	Reason for failure to meet the required service level provide a reason(s) for not giving at least 4 business days' notice of a planned interruption	Remediation provide details of actions taken to rectify the non-compliance and to minimise future occurrences.	
	17229	15/8/23	23	23	Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration.	Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error and installed a temporary label at the fuse. Welfare checks were conducted by phone call to the registered contact for the life support site. Full investigation carried out to determine root cause of incident and identify oportunities for improvement.	
	17255	31/8/23	30	30	An error was made by the electrical officer restoring supply with a step missed in the restoration process that resulted in 30 customers to lose supply.	Electrical officer immediately began the process to restore supply to impacted customers by restoring the LV back-feed and proceeding with correct order of the switching plan. Full investigation carried out to determine root cause of incident and identify oportunities for improvement.	
	Note - this incident was incorrectly paid as a GSL-4, but should have been paid a GSL-2. This has been rectified in September 2024 GSL rebate payments. 17268	7/9/23	1	1	Whilst performing work that required disconnection of a service line from an individual customer premises, an Evoenergy Electrical Officer mistakenly disconnected an adjacent service line resulting in a life support customer losing supply.	The EO restored supply immediately after realising error. The EO completed a welfare check on the life support customer in person, knocking on the door to explain the incident which had occurred, and ensuring the wellbeing of the customer. Full investigation carried out to determine root cause of incident and identify oportunities for improvement.	
	16742	2/11/22	35	35	Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration.	Upon confirmation of the error, the EO restored supply to impacted customers, logged the systems error. Full investigation carried out to determine root cause of incident and identify oportunities for improvement.	
	17538	15/2/24	2	2	Customer notification checks for additional customers were not completed per Evoenergy procedure PO07307, resulting in a Failure to Notify breach.	No immediate rectification action was possible on this occasion as the loss of supply was reported to Evenengy by one impacted customer 4 days after the outage had taken place. Upon receipt of the complaint, Evenengy opened an investigation to identify root cause and coportunities for improvement.	
	17589	19/3/24	13	13	Incorrect labelling at the fuses. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration.	Evoenergy immediately restored supply upon identification of the error. Labels were corrected at the substation. Correct customers were solated and works proceeded per the switching plan. Full investigation carried out to determine root cause of incident and identify oportunities for improvement.	
	17625	7/4/24	54	54	An IT system configuration error resulted in incorrect population of outage start and end times of two seperate outages in the notification generation process. Investigation identified the root cause of the error was an inability of the system to accurately apply daylight savings time zones to the start and end times for the outage. As a result, the start and end time on the notifications generated was one hour after the actual start time of the outage.	No immediate rectification action was possible on this occasion as the loss of supply was reported to Evoenergy by one impacted customer 4 days after the outage had taken place. Upon receipt of the complaint, Evoenergy opened an investigation to identify root cause and opportunities for improvement.	
	17628	12/4/24	30	30	Evoenergy was completing planned network maintenance which required an isolation to facilitate a planned interruption to supply. An Electrical Officer (EQ) was conducting switching operations per the approved switching plan and operated the switch identified to isolate supply to one section. At the time of switching operation, the EO failed to identify that the isolation point was part of a single circuit substation, whereas ADMS systems maps indicated a multi circuit substation. This resulted in the isolation of 2 additional circuits due to the single circuit substation configuration.	Approximately 10 minutes after the isolation had been executed, a customer who had not received notification called to report loss of supply at their premise. Evenergy's control room operator contacted the EO to advise of the incident and authorise network restoration. The EO returned to the substation, identified his error, then followed the instruction per the approved switching plan to restore supply to impacted customers. Full investigation carried out to determine root cause of incident and identify oportunities for improvement.	
	17681	23/5/24	1	1	The cause was confirmed as an inconsistency between the systems maps and the physical network configuration impacting one premise with a Failure to Notify breach. As a result, the customer lost supply for the duration of the planned works; approximately 1 hour and 20 minutes.	Network configuration was confirmed on site by an Electrical Officer, findings were provided to the GIS team to ensure that systems maps were updated with accurate and current information.	
	17714	13/6/24	13	13	Incorrect labelling at the substation. Inconsistency between the Advanced Distribution Management System (ADMS) diagram and the actual physical network configuration which was not identified by scoping in the works planning stages of the outage.	At the time the breach was confirmed, the pillar had already been removed as part of planned network maintenance. The crew continued with the installation of the new pillar to restore supply as soon as possible. Full investigation carried out to determine root cause of incident and identify oportunities for improvement.	
	Note: Press tab on your keyboard to start a new line.						
Duration o B207	f interruptions to utility services (Guaranteed Service level 5) Number of unplanned sustained interruptions that lasted for 12 hours	le l					
6207	or longer		123				
	'Unplanned sustained interruption' means an unplanned interruption to a utility service that has a duration longer than three minutes. For reference, see Dictionary in the Consumer Protection Code 2020.		-				

Please give details on every instance of an unplanned sustained inte	rruption that lasted for 12 hours or le	onger. Also, please provide reason for failure to	meet the required service level and actions	taken to rectify the non-compliance and minim	ise future occurrences.		
Please tick 'Nothing to report' if you have no incident to report. Reference code Your reference code	Date enter as dd/mm/yyyy	Duration of unplanned interruption enter as hours:minutes	Number of premises affected provide the number of customer affected by the interruption	Number of premises that experienced an unplanned sustained interruption that lasted for 12 hours or longer	Did this event occur on a Major Event day (as classified under the AER's distribution reliability measures) Answer Y/N	Reason for failure to meet guaranteed service level provide a reason/s why the unplanned sustained interruption lasted for 12 hours o	Remediation provide details of actions take rectify the non-compliance and minimise future occurrences
150002377	23/7/23	22.18	2	2	N	longer Weather and environment - fire	Identified cause of fault an
151003686	10/8/23	16.25	2,298	1	N	General - No cause found (not in storm	repaired network Cause of fault not found, network restored success
151003812	18/8/23	13.57	9	7	N	Third Party - Vehicle Impact	Identified cause of fault ar
150003254	5/10/23	17.28	1	1	N	Asset Failure - Low Voltage Network	repaired network Identified cause of fault a
150003255	4/10/23	14.17	2	2	N	Asset Failure - Low Voltage Network	repaired network Identified cause of fault a
150003428	12/10/23	42.67	152	2	N	Asset Failure - High Voltage Network	repaired network Identified cause of fault a
151004351	5/12/23	17.33	2	2	N	Asset Failure - Low Voltage Network	Identified cause of fault
151004358	5/12/23	16.68	24	6	N	Asset Failure - Low Voltage Network	repaired network Identified cause of fault
151004300	3/12/23	214.88	1	1	N	Asset Failure - Low Voltage Network	repaired network Identified cause of fault
150004139	19/12/23	24.05	2,242	2	N	Vegetation - Blow or fall into asset	repaired network Tree/branch removed fr
							powerlines and damage equipment repaired/rep
150004297	23/12/23	44.17	1	1	N	Asset Failure - Low Voltage Network	Identified cause of fault
150004434	3/1/24	13.68	23	5	N	Third Party - Vehicle Impact	repaired network Identified cause of fault repaired network
150004472	6/1/24	12.33	17	3	N	Vegetation - Blow or fall into asset	Tree/branch removed fr powerlines and damage equipment repaired/rep
150004622	13/1/24	34.25	2	2	N	Asset Failure - High Voltage Network	Identified cause of faul
150005066	7/2/24	35.93	6	1	N	Asset Failure - Low Voltage Network	repaired network Identified cause of fault
150005139	25/2/24	73.63	3	3	N	Asset Failure - Distribution Substation	Identified cause of fault
150005453	8/03/2024	14.47	8,475	48	N	Asset Failure - Zone Substation	Identified cause of fault
150005370	8/3/24	90.42	2	2	Ν	Asset Failure - Low Voltage Network	Identified cause of fault
150005606	18/3/24	159.82	3	1	N	Asset Failure - Low Voltage Network	Identified cause of fault
150006208	17/4/24	69.12	1	1	N	Asset Failure - Low Voltage Network	Identified cause of fault
150006083	1/4/24	765.22	1	1	N	Third Party - Excavation Impact	Identified cause of fault
151005662	28/5/24	15.98	20	20	N	Asset Failure - Low Voltage Network	Identified cause of fault repaired network
151005400	8/5/24	36.72	221	1	N	Asset Failure - High Voltage Network	Identified cause of fault repaired network
151005820	5/6/24	116.53	1	1	N	Asset Failure - Low Voltage Network	Identified cause of fault repaired network
150006590	28/6/24	23.82	2	1	N	Third Party - Excavation Impact	Identified cause of fault repaired network
151005601	24/5/24	25.77	2,472	1	N	Asset Failure - High Voltage Network	Identified cause of fault repaired network
151005707	31/5/24	62.68	20	4	Ν	Vegetation - Blow or fall into asset	Tree/branch removed fr powerlines and damage equipment repaired/rep
150006590	28/6/24	23.82	2	1	N	Third Party - Excavation Impact	Identified cause of fault
Note: Press tab on your keyboard to start a new line. Number of premises where supply was not restored within 12 hours	of					•	Concurretwork
the initial interuption		123					
Average unplanned interuption duration		72			Hours		
ive duration of interruptions to utility services (Guaranteed Ser Number of properties that experienced <u>20 hours of unplanned</u>	rvice level 6)	25					
sustained interruptions during the reporting year Number of properties that experienced <u>30 hours of unplanned</u>		6					
sustained interruptions during the reporting year							
Number of properties that experienced 60 hours of unplanned sustained interruptions during the reporting year		11					
Provide details of actions taken to minimise future interruptions for the customers who have experienced 20 hours or more of interruptions		in efficiency iniative, PowerUp. The aim of this i rough strategic planning, maintenance and repa					

Frequenc	y of Interruptions (Guaranteed Service level 7)						
B211	Number of customers that experienced more than 9 unplanned		0				
	sustained interruptions during the reporting year						
Response	time to notification of problem or concern (Guaranteed Service	e Level 8)					
B212	Total number of notifications received related to damage to, or a fault	1	749				
	or problem with the utility network.						
B213	Number of notifications related to damage to, or a fault or problem		40				
	with the utility network likely to affect public health, or caused or						
	potentially caused, substantial damage or harm to a person or						
	property (priority 1).						
B214	Number of priority 1 notifications <u>not</u> responded to within six hours.		0				
B214(a)	Please give details on every instance where a priority 1 notification wa	as not responded to within six hours.	Also, please provide reason for failure to mee	et the required service level and action	s taken to rectify the non-compliance and n	ninimise future occurrences.	
	Please tick 'Nothing to report' if you had no incident to report.						
	Reference code Your reference code	Date enter as dd/mm/yyyy	How long before you responded? enter as hours:minutes	Suburb/s or area affected	Number of customers affected	Reason for not meeting the guaranteed service level provide a reason/s why the priority 1 notification was	What was the effect to the customer? We will assess your response as to whether the effect of the incident to the
						not responded to within 6 hours	customer is serious or not.
	Note: Press tab on your keyboard to start a new line.						
B214(b)	Number of times that priority 1 notifications were not resolved within		0				
	the time specified in the response to the customer.						
B215	Number of notifications related to other problems or concerns that		709				
	were not likely to affect public health, or cause or potentially cause						
	substantial damage or harm to a person or property (priority 2).						
B216	Number of priority 2 notifications not responded to within 48 hours.		0				
B217	Number of times that priority 2 notifications were not resolved in the		0				
	time specified in the response to the customer.						

END OF B2



## Part B — Consumer Protection Code

#### B8— Rebates paid against guaranteed service levels

#### Please answer 'n/a' if the question is not applicable. Answer "0" if data recorded is nil or zero .

				Number of ti	mes GSL w	as not met		
Reporting year	Ref	Subject of the service level	Q1	Q2	Q3	Q4	Total	Additional comments
2023-24	GSL-1	Customer connection times	70	58	18	4	150	
2023-24	GSL-2	Wrongful Disconnection	0	1	0	0	1	
2023-24	GSL-3	Responding to complaints	0	0	0	0	0	
2023-24	GSL-4	Notice of planned interruption to services	54	35	15	98	202	
2023-24	GSL-5	Duration of interruption (single)	10	17	65	31	123	
2023-24	GSL-6	Cumulative duration of interruptions	-	-	-	42	42	
2023-24	GSL-7	Frequency of interruptions	0	0	0	0	0	
2023-24	GSL-8	Response time to network problems or concern	0	0	0	0	0	
		Total	134	111	98	175	518	



# Part C – Utilities (Electricity Feed-in Code)

# C1 — Distributor obligations (Clause 4)

Ref	Reporting requirements	Response	Additional comments
Our tracking number		Data must relate only to the 2023-24 reporting period unless specified otherwise.	Please provide information that you feel is relevant to support us in our assessment about the non-compliance and/or variances in numbers from previous years
Distributor	rs Obligations (Clause 4)		
C101	Number of instances where the licensee did not provide the required distributor actions.	0	
C101(a)	Provide a information and reason/s for not meeting the requirement. For example, did the licensee fail to connect an 'eligible entity's compliant generator to the network, or did not reimburse the NERL Retailer for an 'eligible entity' in accordance with the Electricity Feed-in (Renewable Energy Premium) Act 2008.	N/A	
C101(b)	Provide information on actions taken to rectify the non- compliance and minimise future occurrences.	N/A	
C102	Does the licensee's complaints procedures cover disputes or complaints by occupiers of premises relating to the Electricity Feed-in Scheme? (Clause 4.4)	Yes	
C103	Number of complaints received related to the administration of the Feed-in Scheme.	0	
C103(a)	Provide a summary of the common complaints received, and action/s taken to address the complaints.	N/A	



# Part D — Utility licence conditions

<b>Ref</b> Our tracking	Reporting requirements	Response	Additional comments
number		Answer n/a if the data requested is not available.	
		Answer "0" if data recorded is nil or zero. Data must relate only to the 2023-24 reporting period unless specified otherwise.	
	Licensee to notify ICRC of any material breaches (Clause 8.2)		
D101	Number of material breaches of the licensee's licence or any		Please refer to attached letter from
	applicable law, code of practice, directions and guidelines.	1	Evoenergy to the ICRC dated 25 July 2024.
D101(a)	Please provide the dates for each material breach and type of breach	01/03/2023	Ring-fencing Guidelines clause 3.1(b)
D101(b)	Was the Commission notified of the breaches? NB - Immediate		Evoenergy reported this incident to the ICRC
	reporting applies to material breaches, see the ICRC Material Breach Guideline 2021	Yes	on 25 July 2024.
	Licensee to provide statement on any non-compliance (Claus	e 8.3)	
D102	Number of non-compliances with any of the licensee's obligations		Evoenergy proactively monitors and reports
	under clause 6.2 of its licence to comply with the Utilities Act, relevant		on compliance matters and incidents involving
	Industry Codes, relevant Technical Codes, any directions given by the		non-compliance in line with regulatory
	ICRC or any applicable ring-fencing requirements	0	obligations under the Utilities Act, relevant
			industry and technical codes and AER Ring-
			fencing Guidelines.
D102(a)	Provide details of each non-compliance, including actions taken to		N/A
	rectify or minimise the effect of the non-compliance.	N/A	
D102(b)	Was the Commission notified of the non-compliances?	N/A	N/A
	Availability of Utility Licence Annual Report (Clause 8.5)		
D103	Was a summary of the 'Utility Licence Annual Report' (ULAR) for 2022- 23 made publicly available by the licensee?	Yes	Evoenergy publishes it's annual ICRC ULAR reports on it's website.

D103(a)	Please provide the link to the ULAR summary.	https://www.evoenergy.com.au/About- us/Reports-and-publications.	23.24 ICRC ULAR available via this link.
D103(b)	Please confirm that a summary of the 2023-24 ULAR will be published before 30 November this year	Yes	Evoenergy will publish the ULAR summary in line with the obligation under clause 8.5.
	Operation and compliance audits (Clause 8.6)	1	
D104	When was the last time the licensee reviewed its data collection and reporting process?	Evoenergy reviews its data collection and reporting processes annually.	N/A
D105	How often does the licensee audits or review its data collection and reporting process?	Evoenergy reviews its data collection and reporting processes via annual management system audits.	N/A
Click bara f	<b>Technical and prudential criteria (Clause 9)</b> for a copy of the Commission's Technical and prudential criteria guideline		
D106	Please provide a summary of details of the licensee's financial and technical capacity for which show it can continue to provide the services authorised in the licence.	Please refer to attached document ActewAGL Distribution SPFR (2023) Final with auditors report.	Please note this document is confidential and only for purpose of the commissioners use.
	Charge and assignment (Clause 11)		
D107	Were there any significant transfers in shareholdings (involving more than 50% of the shares) or changes in ownership in ?	No	N/A
D107 (a)	If yes, please provide details.	N/A	N/A
	Record keeping (Clause 14)		
D108	Has the licensee kept or caused to be kept, comprehensive records in accordance with Commission's requirements under the Utilities Act?	Yes	Evoenergy keeps records in line with it's regulatory obligations.
	Emergency telephone service (Schedule 1: Clause 1)	l 	
D109	Did the licensee maintain a 24 hour emergency telephone service that was accessible to the public every day of the year and able to receive reports of network emergencies?	Yes	Evoenergy's Faults Call Centre is available to the public 24 hours a day, every day of the year.

D109(a)	How are customers and the public informed of the service?	Evoenergy utilises various resources to inform the public of this service.	Customers and the public are informed of the service via Evoenergy's website, the Yellow Pages business directory, which includes multiple listings for Evoenergy (online and print), customer notifications, Evoenergy broadcast and print safety campaigns, social media messaging, signage on Evoenergy assets and government and retailer websites e.g. www.accesscanberra.com.au	
	Network losses (Schedule 1: Clause 2)			
D110	Please provide details of strategies employed to cost effectively minimise losses of electrical power in the licensee's network	Evoenergy is actively involved in developing Demand Side Management and Embedded Generation opportunities. The Future energy page on Evoenergy's website covers a range of initiatives.	https://www.evoenergy.com.au/Future- energy	
	Requirements under the Electricity Feed-in Scheme (Schedu	le 1: Clause 3)		
D111	Number of non-compliance under the Electricity Feed-in (Renewable Energy Premium) Act 2008	0	N/A	
D111(a)	Provide details of the non-compliance/s and actions taken to rectify the non-compliance/s.	N/A	N/A	
	END OF D1			



# Authorising and contact officers

# Authorising officer

The licensee's officer authorising the release of this information is

Name	Peter Billing
Title/position in organisation	General Manager - Evoenergy
Postal address	40 Bunda Street, Canberra Australian Capital Territory 2601
Telephone	02 6293 5850
Email	peter.billing@evoenergy.com.au

## **Contact officer**

The licensee's contact officer for regulatory and compliance matters is

Name	Jane Godkin
Title/position in organisation	Regulatory Technical Compliance Manager - Strategy and Operations
Postal address	40 Bunda Street, Canberra Australian Capital Territory 2601
Telephone	02 6248 3453
Email	jane.godkin@evoenergy.com.au